Message Text

UNCLASSIFIED

PAGE 01 MBABAN 01577 181601Z

70

ACTION SY-05

INFO OCT-01 AF-06 ISO-00 A-01 ABF-01 SS-15 USIA-15 SCCT-01

FBO-06 SCA-01 OC-05 CCO-00 SCSE-00 /057 W

----- 022539

R 181301Z SEP 75

FM AMEMBASSY MBABANE TO SECSTATE WASHDC 8546 INFO AMEMBASSY GABORONE AMEMBASSY PRETORIA

UNCLAS MBABANE 1577

E.O. 11652: N/A TAGS: ASEC

SUBJ: SECURITY IMPROVEMENTS TO AMBASSADOR'S RESIDENCE AND USG INSTALLATIONS

REF: A. STATE 210312 B. STATE 211364 C. MBABANE 1527 D. MBABANE 1540

- 1. AS NOTED IN REFTELS C AND D, EMBASSY PSO AND RSO, PRETORIA HAVE DETERMINED THAT THE APPLICATION OF MYLAR TO GLASS AREAS OF THE AMBASSADOR'S RESIDENCE, THE CHANCERY, UNCLASSIFIED WIREROOM AND USIS READING ROOM, IS NECESSARY TO COMPLETE PROPER SECURITY POSTURE.
- 2. EMBASSY MBABANE WILL NEED MYLAR FOR 1100 SQUARE FEET OF GLASS SURFACE, WITH AN ADDITIONAL 10 PERCENT TO COVER WASTEAGE. THE ESTIMATED COST OF THIS MATERIAL FROM MADICO, WOBURN, MASSACHUSETTS IS DOLLARS 653, NOT RPT NOT INCLUDING SHIPPING CHARGES.
- 3. IN LIGHT OF REFTELS A AND B, AND THE NECESSITY FOR THE RECOMMENDED SECURITY IMPROVEMENTS, REQUEST DEPARTMENT FUND CITATION FOR DOLLARS 1,000 FOR COST OF MYLAR AND SHIPMENT TO MBABANE ASAP. LANE

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 MBABAN 01577 181601Z

UNCLASSIFIED		
NNN		

Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 06 JUL 2006

Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

Current Classification: UNCLASSIFIED

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 18 SEP 1975 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a Disposition Approved on Date: Disposition Authority: n/a Disposition Case Number: n/a

Disposition Camment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a

Disposition Reason: Disposition Remarks:

Document Number: 1975MBABAN01577
Document Source: CORE
Document Unique ID: 00

Drafter: n/a Enclosure: n/a Executive Order: N/A Errors: N/A

Film Number: D750324-0398

From: MBABANE Handling Restrictions: n/a

Image Path:

Legacy Key: link1975/newtext/t19750940/aaaabjbw.tel Line Count: 60

Locator: TEXT ON-LINE, ON MICROFILM

Office: ACTION SY Original Classification: UNCLASSIFIED Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: n/a
Previous Classification: n/a Previous Handling Restrictions: n/a

Reference: 75 STATE 210312, 75 STATE 211364, 75 MBABANE 1527

Review Action: RELEASED, APPROVED

Review Authority: izenbei0 Review Comment: n/a
Review Content Flags: Review Date: 01 JUL 2003

Review Event:

Review Exemptions: n/a
Review History: RELEASED <01 JUL 2003 by MaustMC>; APPROVED <20 JAN 2004 by izenbei0>

Review Markings:

Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 06 JÚL 2006

Review Media Identifier: Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: SECURITY IMPROVEMENTS TO AMBASSADOR'S RESIDENCE AND USG INSTALLATIONS TAGS: ASEC
To: STATE

Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 06 JUL 2006